

FIG. 1

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	0	0	0	0	0	0
					0	64
					32	32
					16	96
					48	16
					8	80
					24	48
					56	112
				8	8	8
					72	40
					40	104
					24	24
					88	56
					56	120
			4	4	4	4
					68	36
					36	100
					20	20
					84	52
					52	116
				20	12	12
					76	44
					44	108
					28	28
					92	60
					60	124

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	2	2	2	2	2	2
					66	34
					34	98
					18	18
					82	50
					50	114
				18	10	10
					74	42
					42	106
					26	26
					90	58
					58	122
			10	10	6	6
					70	38
					38	102
					22	22
					86	54
					54	118
				22	14	14
					78	46
					46	110
					30	30
					94	62
					62	126

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	1	1	1	1
					65	33
					33	97
					17	17
					81	49
					49	113
				17	9	9
					73	41
					41	105
					25	25
					89	57
					57	121
			9	9	5	5
					69	37
					37	101
					21	21
					85	53
					53	117
				21	13	13
					77	45
					45	109
					29	29
					93	61
					61	125

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	3	3	3	3
					67	35
					35	99
					19	19
					83	51
					51	115
				19	11	11
					75	43
					43	107
					27	27
					91	59
					59	123
			11	11	7	7
					71	39
					39	103
					23	23
					87	55
					55	119
				23	15	15
					79	47
					47	111
					31	31
					95	63
					63	127

FIG. 2




FIG. 3




FIG. 4